

- The Textile Machinery Manufacturers Association (India) vide their letter No. PRO/8/2006-07/576 dated 18/08/2006 informed the production of ring frames by the various manufacturers in India as 2093232 spindles. The details are as under:

Production of Ring Frames during 2005-06							
Sr. No	Name of the Manufacturers		April to June	July to Sept.	Oct. to Dec.	Jan - March	Total
1	Lakshmi Machine Works Ltd.,	No. of Machines	385	390	433	471	1679
		No. of Spindles	373728	392448	450240	490848	1707264
2	Kirloskar Toyoda Textile M/c Ltd	No. of Machines	51	63	63	65	242
		No. of Spindles	54768	65232	71040	74928	265968
3	Suessen Asia Ltd.	No. of Machines	30	30	30	30	120
		No. of Spindles	30000	30000	30000	30000	120000
	No. of Machines		466	483	526	566	2041
	No. of Spindles		458496	487680	551280	595776	2093232

Ref: Noting dated 24/08/2006 in file no. 42 (11)/2006/IMSC/WVG/Vol III

- In case the Indian machinery manufacturers keep the manufacturing capacity at the rate of 2 Million spindles annually as constant irrespective of the various odds as may be faced by them, there may be a shortfall of 1.8 Million spindles annually required for the modernization which have to be met by importing the same from the overseas suppliers. If the textile manufacturers require to produce quality yarn and sustain in the global market and willing to go for installation of the machines having state of the art technology, they may visit the various websites as given for the purpose.**